

ERRATUM / ERRATUM


Erratum: Flow over a stepped chute with and without macro-roughness elements

Mehmet Ali Kökpinar

Ref.: Can. J. Civ. Eng. **31**: 880–891 (2004).

In the above paper, the following errors occurred: (1) On page 880, the doi should be doi: 10.1139/L04-059, (2) in Fig. 3, page 885, (d), (e), and (f) are missing, and (3) in Fig. 10, page 889, the label should read: — eq. [8] for WMR. The corrected version of Fig. 10 appears below and Fig. 3 follows on the next two pages.

Fig. 10. Comparison of fz_c/V_c versus C data with the data of Chanson and Toombes (2002a) for WMR step configuration and $q = 0.15 \text{ m}^2/\text{s}$.



Received 2 August 2005. Accepted 2 August 2005. Published on the NRC Research Press Web site at <http://cjce.nrc.ca> on 21 September 2005.

M.A. Kökpinar. Hydraulics Laboratory, Technical Research and Quality Control Department, State Hydraulic Works, 06100 Yüce-tepe, Ankara, Turkey (e-mail: mkokpinar@superonline.com).

Fig. 3. Flow regimes over various step configurations for $q = 0.06 \text{ m}^2/\text{s}$: (a) WMR, (b) MR, and (c) AMR; and for $q = 0.20 \text{ m}^2/\text{s}$: (d) WMR, (e) MR, and (f) AMR.




Fig. 3 (concluded).

(d)




-----Pseudo -bottom

(e)



-----Pseudo -bottom

(f)



-----Pseudo -bottom